




FORM 1

ARCHITECT'S CERTIFICATE

Date: 31March 2018

To,
Casadelsogno Development Company Ltd.
C/O Nitya Resort, Naikawaddo,
Calangute Bardez, - Goa 403507

Subject: Certificate of Percentage of Completion of Construction Work of the Six (6) no. of Villas of the Project situated on the Plot bearing Survey no. 33 Sub-division no. 1 demarcated by its boundaries North by proposed 10 m wide road, towards the South property bearing Survey no. 31/1 towards the East by property bearing Survey no 32/1 and 32/2 towards the West by property bearing survey nos. 31/1 and 29/2 of Nagoa Village Panchayat, Bardez Taluka North- Goa District , admeasuring 1875.00 sq.mts. Area being developed by Casadelsogno Development Company Ltd.

Ref: Goa RERA Registration Number: _____

Sir,

I, Ashwinikumar Prabu have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the Six (6) no. of Villas of the Entire Phase of the Project, situated on the plot bearing, PTS, Chalta No./Survey no./ Plot no Survey no. 33 Sub-division no.1 of Nagoa Village Panchayat, Bardez Taluka North- Goa District PIN 403521 admeasuring 1875 sq.mts. area being developed by Casadelsogno Development Company Ltd.

1. Following technical professionals are appointed by Owner / Promoter :—
 - (i) Shri Ashwinikumar Prabu as Architect
 - (ii) Shri Rajesh Mahambrey as Structural Consultant / Engineer
 - (iii) M/s /Shri / Smt. _____ as MEP Consultant
 - (iv) M/s /Shri / Smt. _____ as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered *vide* number _____ under GoaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.




TABLE-B

Internal and External Development Works in respect of the entire Registered Phase.


S.No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1.	Internal Roads & Pathway.	Yes	0 %	
2.	Water Supply	Yes	0 %	
3.	Sewerage (chamber, lines, Septic Tank, STP).	Yes	0 %	
4.	Storm Water Drains	Yes	0 %	
5.	Landscaping & Tree Planting.	Yes	0 %	
6.	Street Lighting	Yes	0 %	
7.	Community Buildings	Yes	NA	
8.	Treatment and disposal of sewage and sullage water.	No	NA	
9.	Solid Waste management & Disposal.	NA	NA	
10.	Water conservation, Rain water harvesting.	NO	NA	
11.	Energy management	NO	NA	
12.	Fire protection and fire safety requirements	NO	NA	
13.	Electrical meter room, sub-station, receiving station.	Yes	0 %	
14.	Others Swimming Pool & Club House	Yes	0%	

Yours Faithfully,

ARCH. ASHWINIKUMAR PRABHU

TCP Reg. No. AR/0029/2010

COA Reg. No. CA/97/21951




C-5, 3rd floor, Trionora Apts., Near Municipal Market,
Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330
B-209, 2nd floor, Saldanha Business Towers, At Court Circle,
Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell : 9422445450
email : studioarchetype@gmail.com
web : http://www.studioarchetype.co.in

TABLE-A

Villa – A

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3) number of Slabs of Super Structure	35%
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0%
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %




C-5, 3rd floor, Trionora Apts., Near Municipal Market,
Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330
B-209, 2nd floor, Saldanha Business Towers, At Court Circle,
Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell : 9422445450
email : studioarchetype@gmail.com
web : http://www.studioarchetype.co.in

TABLE-A

Villa – B

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3 number of Slabs of Super Structure	70 %
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %



C-5, 3rd floor, Trionora Apts., Near Municipal Market,
Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330
B-209, 2nd floor, Saldanha Business Towers, At Court Circle,
Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell : 9422445450
email : studioarchetype@gmail.com
web : http://www.studioarchetype.co.in

TABLE-A

Villa – C

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3) number of Slabs of Super Structure	70%
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %





TABLE-A

Villa - D

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3) number of Slabs of Super Structure	70%
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %




C-5, 3rd floor, Trionora Apts., Near Municipal Market,
Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330
B-209, 2nd floor, Saldanha Business Towers, At Court Circle,
Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell : 94224454
email : studioarchetype@gmail.co
web : http://www.studioarchetype.co

TABLE-A

Villa – E

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3) number of Slabs of Super Structure	100%
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	10%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %



C-5, 3rd floor, Trionora Apts., Near Municipal Market,
Panaji - Goa 403 001 INDIA Ph.: 0091 832 6511330
B-209, 2nd floor, Saldanha Business Towers, At Court Circle,
Mapusa, Goa, 403507 INDIA Ph.: 0091-832-6516650

Cell : 9422445450
email : studioarchetype@gmail.com
web : http://www.studioarchetype.co.in

TABLE-A

Villa – F

Sr. No.	Tasks /Activity	Percentage of work done
1.	Excavation	100%
2.	One (1) number Plinth	100%
3.	Nil number of Podiums	NA
4.	Stilt Floor	NA
5.	Three (3) number of Slabs of Super Structure	100%
6.	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	10%
7.	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %
8.	Staircases, Lifts Well sand Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %
9.	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %