Ar. Bansri S.

Kumath

New Lines In Architecture

Date: 01/12/2020

#### FORM 1

#### ARCHITECT'S CERTIFICATE

To,

Milroc Good Earth Developers, 501, Fifth Floor, Milroc Lar Menezes, S. V. Road, Panaji, Goa.

Subject: Certificate of Percentage of Completion of Re-development of Existing Adarsh Co. Op. Housing Society Ltd. project for Construction of Residential Building situated on the property bearing Chalta No.5to19, 36, P.T. S.NO.143, City Survey - Panji, Tal. Tiswadi, Goa demarcated by its boundaries On the North: By 25 meters wide road and by an access

On the South: By properties bearing P.T. Sheet No.143 Chalta No. 30 and 31 of the city survey, Panaji, Goa On the East: By properties bearing P.T. Sheet No. 143 Chalta No. 20 and 27 of the city survey, Panaji, Goa. On the West: By properties bearing survey No. 3/1, 3/2 and 3/4 of the village Taleigao, Tiswadi, Goa. Of Municipal Corporation of the city of Panaji, Taluka Tiswadi, District North Goa, PIN 403001, admeasuring 6887.00Sq.mts. area being developed by Milroc Good Earth Developers.

Ref:	Goa	RERA	Registration	Number	
------	-----	------	--------------	--------	--

Sir,

I Sumit Kumath, have undertaken assignment, as Architect for certifying Percentage of Completion of Construction Work of the 6 Buildings of the Project, "Adarsh Co-operative Housing Society Limited, a project by Milroc Good Earth Developers", situated on the Property bearing Chalta No. 5 to 19, 36 P.T.S. No. 143, City survey Panaji-Goa, Tiswadi taluka, Goa, admeasuring 6887.00sq.mts. area being re-developed by Milroc Good Earth Developers.

- 1. Following technical professionals are appointed by Owner / Promoter:
  - (i) Shri Sumit Kumath as Architect,
  - (ii) Shri. G.A. Bilare as Structural Engineer,
  - (iii) M/s MEP System Solutions Pvt. Ltd. as MEP Consultant,
  - (iv) Shri. Rateesh Rivankar as Project incharge

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered *vide* number-------under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Mumbai

Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88. Pune

8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-05. Goa B-

105, Milroc Woods, Old Goa, Panjim-02. Nashik 9B, Anudeep Park, Tidke Colony,

Nashik.

A/2003/3232

# Ar. Bansri S. Kumath

New Lines In Architecture

#### TABLE A-1

#### **BLOCK A**

Sr No	Tasks /Activity	Percentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	

Mumbai Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88. Pune 8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5. Goa B-105, MilrocWoods, Old Goa, Panjim-02.

CAI2003/32323

Nashik 9B, Anudeep Park, Tidke Colony, Nashik.

New Lines In Architecture

#### TABLE A -2

### BLOCK B

Sr No	Tasks /Activity	Percentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	



Mumbai

Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88.

Pune

8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-05.

Goa

B-105, MilrocWoods, Old Goa, Panjim-02. Nashik

9B, Anudeep Park, Tidke Colony, Nashik.

#### TABLE A -3

### BLOCK C

Sr No	Tasks /Activity	Percentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	



Mumbai

Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88.

Pune

8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5.

Goa B-

105, Milroc Woods, Old Goa, Panjim-02. Nashik

9B, Anudeep Park, Tidke Colony, Nashik.

## Ar. Bansri S. Kumath

New Lines In Architecture

#### TABLE A -4

### BLOCK D

Sr No	Tasks /Activity	Percentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	



Mumbai Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88.

Pune

8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5.

Goa

B-105, Milroc Woods, Old Goa, Panjim-02. Nashik

9B, Anudeep Park, Tidke Colony, Nashik.

# Ar. Bansri S. Kumath

### New Lines In Architecture

### TABLE A -5

#### BLOCK E

Sr No	Tasks /Activity	ercentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	



Mumbai

Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88. Pune

8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5. Goa

B-105,MilrocWoods, Old Goa,Panjim-02. Nashik

9B, Anudeep Park, Tidke Colony, Nashik.

# Ar. Bansri S. Kumath

New Lines In Architecture

#### TABLE A -6

#### BLOCK F

Sr No	Tasks /Activity	Percentage of work done	
1	Excavation	0 %	
2	1 Number of Basement and Plinth	0 %	
3	0 Number of Podiums	NA	
4	1 Number of Ground Floor	0 %	
5	10 number of Slabs of Super Structure	0 %	
6	Internal Walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises.	0 %	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises.	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks.	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing.	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to obtain Occupation / Completion Certificate.	0 %	



Mumbai

Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88. Pune 8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5. Goa B-105,MilrocWoods, Old Goa,Panjim-02. Nashik 9B, Anudeep Park, Tidke Colony, Nashik.

Ar. Bansri S.

Kumath

New Lines In Architecture

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

S.No.	Common areas and Facilities,	Proposed	0	Details
	Amenities	(Yes/No)	Work done	
1	Internal Roads & Footpaths	Yes	0 %	
2	Water Supply	Yes	0 %	
3	Sewerage (Septic Tank, STP).	No	0 %	
4	Storm Water Drains	Yes	0 %	
5	Landscaping & Tree Planting.	Yes	0 %	
6	Street Lighting	NA	NA	
7	Community Buildings	Yes	0 %	
8	Treatment and disposal of sullage water.(Grey water treatment)	Yes	0%	
9	Solid Waste management & Disposal.	Yes	0%	
10	Water conservation, Rain water harvesting.	Yes	0 %	
11	Energy management (Solar panel for hot water)	Yes	0%	
12	Fire protection and fire safety requirements	Yes	0 %	
13	Electrical meter room, substation, receiving station	Yes	0 %	
14	Others ( Option Add more)	NA	NA	

Yours Faithfully

AR. SUMIT KUMATH (License NO CA/2003/32323)

CA/2003/32323

Mumbai Unit 8B, 2<sup>nd</sup> floor, Majithia Ind Estate, Chembur-88. Pune 8, Satpute Bhavan, Tanajiwadi Rd, Shivaji Nagar-o5. Goa B-105,MilrocWoods, Old Goa,Panjim-o2. Nashik 9B, Anudeep Park, Tidke Colony, Nashik.