# Rajesh Mahambrey & Associates

#### **Consulting Structural Engineers**

B-102,1" Floor, Saldanha Business Towers, at Court Circle, Mapusa - Goa - 403,507. **2** 0832-6511692 | Email:-rajeshmahambrey1@gmail.com

#### **ARCHITECT'S CERTIFICATE**

Date: 21/07/2021

To,

M/s. Jaglax Realty Pvt. Ltd. c/o T-16, Andheria More Mehrauli, New Delhi.

> Subject :Certificate of Percentage of Completion of Construction Work of four (4) villas of the entire phase of the project "Mar Selva" situated on the plot bearing Survey no. <u>117/21</u> demarcated by its boundaries property bearing <u>survey no. 117/20 to the</u> <u>North</u>, property <u>by Rivulet/water drain to the South</u>, property bearing <u>survey no. 115/1</u> to the East, property <u>by Rivulet/water drain to the West</u>, of Marna village Panchayat, Taluka Bardez, District North Goa, PIN 403517 admeasuring 2200 sq.mts. area being developed by <u>M/s</u>. Jaglax Realty Pvt. Ltd.

Ref: Goa RERA Registration Number:

Sir,

I Rajesh Mahambrey have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the 4 villas of the entire Phase of the project "Mar Selva", situated in the plot bearing Survey no.<u>117/21</u> of Marna village Panchayat, Taluka Bardez, District North Goa, PIN 403517 admeasuring 2200 sq.mts. area being developed by <u>M/s. Jaglax Realty Pvt. Ltd.</u>

1. Following technical professionals are appointed by Owner / Promoter :-

(i) Shri Rajesh Mahambrey as Architect.

(ii) Shri Rajesh Mahambrey as Structural Consultant.

(iii) M/s \_\_\_\_\_ as MEP Consultant.

(iv) Shri as Site Supervisor.

Based on site inspection, with respect to each of the building of the aforesaid real estate project, I certify that as on the date of this certificate, the percentage of work done for each of the building of the Real Estate Project as registered vide number --- under Goa RERA is as per Table A herein below.

The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

RAJES'H MAHAMBREY (B.E.Civil) No.: SE/0044/2010 Reg B-102, 1st Floor, Saldanha Business Towers, At Court Circle, Mapusa, Goa, 403 507

## <u>Table A</u>

### Villa 01

00%       00%       00%       NA       Inte       00%       inte       00%       iter       Electrical       00%
Ire 00% Ings within 00%
ngs within 00%
ngs within 00%
ngs within 00%
ngs within 00% s to each of the
00%
emises, Electrical
each Floor level 00% nead and Underground
aster, elevation, 00% fing of the Building.
Fighting Fittings and al fittings to Common Compliance to , Finishing to entrance reas appurtenant to all other requirements on /Completion00%

AJESHWAHAMBREY (BUT COM) E-102, 151 P. OF Saldanha Businges Towars, At Court Circle, Mapusa, Goa, 403 507 RAJ

## Table A

### Villa <u>02</u>

<u> </u>	T 1 /4 / .: 4.	Percentage of work
Sr. No	Tasks /Activity	done
1	Excavation	00%
2	One (1) number of Plinth	00%
3	NIL number of Podiums	NA
4	Stilt Floor	NA
5	Two number of Slabs of Super Structure	00%
6	Internal walls, Internal Plaster, Floorings within Rooms/Premises, Doors and Windows to each of the Room/Premises	00%
7	Sanitary Fittings within the Room/ Premises, Electrical Fittings within the Room / Premises.	00%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	00%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building.	00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	00%

HLG. No. SE/0644/2010 (S.E.Civil) Bild2, 1st Floct, Saldanha Business Towers, At Court Circle, Mapusa, Goa, 403 507 RAJESH N

# Table A

### Villa <u>03</u>

		Percentage of work
Sr. No	Tasks /Activity	done
1	Excavation	00%
2	One (1) number of Plinth	00%
3	NIL number of Podiums	NA
4	Stilt Floor	NA
5	Two number of Slabs of Super Structure	00%
6	Internal walls, Internal Plaster, Floorings within Rooms/Premises, Doors and Windows to each of the Room/Premises	00%
7	Sanitary Fittings within the Room/ Premises, Electrical Fittings within the Room / Premises.	00%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	00%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building.	00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	00%

JESH MAHAMBREY (B.E.Civil) Reg. No.: SE/0044/2010 D-102, 1st Flocs Stoacha Business Towers, At Court Circls, Mapusa, Gen, 403 597 R

### Table A

Villa	04
-------	----

Sr. No	Tasks /Activity	Percentage of work done
1	Excavation	00%
2	One (1) number of Plinth	00%
		NA
3	NIL number of Podiums	NA
4	Stilt Floor	00%
5	Two number of Slabs of Super Structure	00%
6	Internal walls, Internal Plaster, Floorings within Rooms/Premises, Doors and Windows to each of the	00/1
7	Room/Premises Sanitary Fittings within the Room/ Premises, Electrical	00%
/	Fittings within the Room / Tenneou	00%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground	
9	Water Tanks The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building.	00%
	completion of terraces with waterp	00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	

RAJESH MAHAMBREY (B.E.Civil) Fleg. No. SE/0044/2010 B-402, 1st Flact, Sadama Duciness Towers, At Court Circle, Mapusa, Goa, 403 507

### **TABLE-B**

Sr. No	Common areas and Facilities, Amenities	Proposed	Percentage of work done	Details
1	Internal Roads & Footpaths	(Yes/No) Yes	00%	
2	Water Supply	Yes	00%	
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	00%	
4	Storm Water Drains	Yes	00%	
5	Landscaping & Tree Planting	Yes	00%	
6	Street Lighting	Yes	00%	
7	Community Buildings	No	00%	
8	Treatment and disposal of sewage and sullage water	Yes	00%	
9	Solid Waste management & Disposal	No	00%	
10	Water conservation, Rain water harvesting	No	00%	
11	Energy management	No	00%	
12	Fire protection and fire safety requirements	No	00%	
13	Electrical meter room, sub-station, receiving station	Yes	00%	
14	Others (Option to Add more)	Yes	00%	

Internal & External Development Works in Respect of the entire Registered Phase

Yours Faithfully,

I

Signature of Engineer T.C.P Reg. No: - SE/0044/2010 AJESH MAHAMBREY (B.E.Civil) Reg. No.: SE/004 1/2010 B-102, 1st Floor Saldanha Business Triwers, At Court Circle, Mapusa, Goa, 403 507 R