

FORM 1 (See Rule 5 (1) (a) (ii)) ARCHITECT'S CERTIFICATE

Date:02/03/2019

To,
Jai Ganesh Ispat And Ferro Alloys Pvt.Ltd.
Represented By POA Prabhu Realtors
Shop No.1, Murgao Avenue,
Nr.Desterro Church, Vasco-Goa.

Subject: Certificate of Percentage of completion of Construction Work of Block A and Block B of entire Phase of the Project Prabhu's Signature [Goa RERA registration Number:Not Allotted] situated in plot bearing Survey no.8/1-B demarcated by its boundaries by Survey No. 8/1A and Plots E-3 & E-4 of Survey No. 8/1 of Chicalim Village to the North, by NH-17B to the South, by 8.00 metres wide internal road & partly by open space and portion of land bearing Survey No. 8/1A of Dabolim Village to the East, by property bearing Survey No. 8/1 of Chicalim Village to the West of Ward - 4, village Dabolim, Taluka Mormugao, District South Goa, Pin 403801 admeasuring 6975.00 sq.mts area being developed by Jai Ganesh Ispat And Ferro Alloys Pvt.Ltd. Represented By POA Prabhu Realtors.

Ref: Goa RERA Registration Number: Not Allotted.

Sir,

I Kundan V.Prabhu have undertaken assignment as Architect of certifying percentage of Completion of Construction Work of Block A and Block B of entire Phase of the Project Prabhu's Signature, situated in plot bearing Survey no.8/1-B of Ward - 4, Village Dabolim, Taluka Mormugao, District South Goa, Pin 403801 admeasuring 6975.00 sq.mts. area being developed by Jai Ganesh Ispat And Ferro Alloys Pvt.Ltd. Represented By POA Prabhu Realtors.

- 1. Following Technical Professionals are appointed by Owner/Promoter:
 - i. Shri Kundan V. Prabhu as Architect
 - ii. Shri Abhay Kunkoleinkar as Structural Consultant
 - iii. Shri Satish Rao as MEP Consultant
 - iv. Shri Sidhalingayya Hiremeth as Site Supervisor

Based on site Inspection, with respect to the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for the Building of the Real Estate Project as registered vide number:Not Allotted under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Note: Above certificate has been made based on the data provided by Promoter and Project Engineer and visual inspection carried out on site.

Date:

Ref:

Project UID No:

TABLE-A						
Sr. No.	Tasks/ Activity	Percentage of work done 0%				
1	Excavation					
2	Basement(s) and Plinth	0%				
3	Podiums	0%				
4	Stilt Floor	0%				
5	Slabs of Superstructure	0%				
6	Internal Walls	0%				
7	Internal Plaster	0%				
8	Flooring within Flats/Premises	0%				
9	Doors to each of Flat/ Premises	0%				
10	Windows to each of Flat/ Premises	0%				
11	Sanitary fittings within the Flat/ Premises	0%				
12	Electrical fittings within the Flat/ Premises	0%				
13	Staircase	0%				
14	Overhead and Underground Tanks	0%				
15	External Plumbing	0%				
16	External Plaster	0%				
17	Floors Elevation/External Plaster	0%				
18	Terraces with waterproofing of the Building	0%				
19	Installation of lifts, escalation etc.	0%				
20	Water Pumps	0%				
21	Firefighting fittings and equipment as per CFO NOC	0%				
22	Electrical fittings to common areas	0%				
23	Mechanical equipment	0%				
24	Environment/CRZ NOC/ Clearance Measures	0%				
25	Entrance lobby/s	0%				
26	Plinth Protection	0%				
27	Paving of areas apartment to building /wing	0%				
28	Compound wall	0%				

	TA	BLE-B		e entire		
Internal & External Development works in respect of the entire registered phase						
Sr. No.	Common areas and Facilities Amenities	Proposed (Yes/No)	Percentage of work done			
		YES	0%			
	Internal roads & rootput	YES	0%			
2	Water SUDDIV	YES	0%			
3	Sewerage (chamber/line)	YES	0%			
4	Sewerage (STP)	YES	0%			
5	Storm water Drains	YES	0%			
6	Landscaping	YES	0%			
7	Tree Planting	YES	0%			
8	Street Lighting	YES	0%			
9	Community Buildings	YES	0%			
10	Treatment and disposal of		0%			
11	Solid waste management &	YES		-		
	disposal	NO	0%	-		
12	Water conservation	YES	0%	-		
13	Rain water harvesting	NO	0%	-		
14	Energy management		0%			
15	Fire protection and fire safety requirement	The same of	0%			
15	Electrical room	YES	0%			
16	Receiving stations	YES	0%	The same of the same		
17	Swimming pool	YES	1070	THE REAL PROPERTY.		

Yours Faithfully,

ARCHITECT & INTERIOR DESIGNER
CA/94/17396
AR/0073/2010

Kundan V. Prabhu COA Registration No: CA/94/17396