



N



SITE PLAN

OF THE PROPERTY BEARING SURVEY NO.62/1 OF VILLAGE MARNA OF TALUKA BARDEZ SHOWING THEREIN THE SUPERIMPOSED POSITION OF EXISTING GROUND CONDITION OVER SURVEY PLAN

SCALE 1:500



AREA OF THE PLOT AS SURVEY PLAN 2300 SQMTS

LEGEND	
	LINE DENOTE SURVEY PLAN
	LINE DENOTE EXISTING ROAD
	LINE DENOTE EXISTING COMPOUNDWALL
	LINE DENOTE DEMOLISED STRUCTURE
	LINE DENOTE EXISTING NALLA EDGE
	LINE DENOTE EXISTING WELL
	LINE DENOTE EXISTING LOSE STONE WALL
	DENOTE OTHER TREES
	DENOTE MANGO TREES
	DENOTE COCONUT TREE

