ARCHITECT'S CERTIFICATE



Date: 11th June 2021

To Mr. Dinesh Suresh Dhanwani & Others, Flat No. 1, Poonam Society, Near UMC,HDFC Bank, Ulhasnagar-3, Thane, Maharashtra

Subject: Certificate of percentage of Completion of Construction Work of Residential Building & Swimming pool of the project "KESHAVA PRESTIGE" situated on the plot bearing survey no. 95/10 by its boundaries.

North By Property surveyed under Sy. No. 106

East By Property surveyed under Sy. No. 95/11

West By Property surveyed under Sy. No. 95/9

South By Property B.B. Borkar road

South ___ by Froperty b.b. Bornai 12au

of Salvador-do-Mundo, Village, Bardez Taluka, admeasuring 975.00 sq.mts owned by Mr. Dinesh Suresh Dhanwani & others out of which 975.00 sq.mts. being developed by Mr. Dinesh Suresh Dhanwani & others.

Ref: Goa RERA Registration Number _____

Sir,

I Mr. Prashant Gaonkar have undertaken assignment as an Architect of certifying Percentage of Completion of Construction Work of the **KESHAVA PRESTIGE** Project, situated on the plot bearing survey no. 95/10, Salvador-do-Mundo, Village, Bardez Taluka, admeasuring 975.00 sq.mts owned by **Mr. Dinesh Suresh Dhanwani & others** out of which 975.00 sq.mts. being developed by **Mr. Dinesh Suresh Dhanwani & others**

- 1. Following technical professionals are appointed by Owner / Promoter:-
 - (i) Prashant Gaonkar an Architect;
 - (ii) Viraj Paraz as Structural Consultant
 - (iii) _____as MEP Consultant
 - (iv) Manish Dalvi as Site Supervisor

Based on Site Inspection, with respect to each of the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered vide number _____ under Goarera is as per Table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

COA REG. NO. CA/97/21582 TCP REG. NO. AR/0064/2010 A-308, Third Floor, Dwarkanth Centre, Above Hotel Navtara, Opp. Shree Bodgeshwar Temple, Mapusa-Goa. Ph.: 9822488590 Off.no.: (0832) 2256590 Email: percent@rediffmail.com

Table A Building of the Project KESHAVA PRESTIGE

| Sr. No. | Tasks /Activity | Percentage of work done | |
|---------|---|----------------------------|--|
| 1 | Excavation | | |
| 2 | 01 numbers of Plinth | 0% | |
| 3 | | 0% | |
| | 01 number of Podiums | 0% | |
| 4 | Stilt Floor | N.A | |
| 5 | 04 number of Slabs of Super Structure | 0% | |
| 6 | Internal walls: Internal Plaster: Floorings within Flats/Premises: Doors and Windows to each of the Flat/Premises: | 0% 0% 0% | |
| 7 | Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises | 0% | |
| 8 | Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks | 0% | |
| 9 | The external plumbing and external plaster: Elevation: Completion of terraces with waterproofing of the Building / Wing: | 0% 0% 0% | |
| 10 | Water pumps: Electrical fittings to Common Areas: Plinth protection: Paving of areas appurtenant to Building/Wing: Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate: | 0% 0% 0% 0% 0% | |

PRASHANT GAONKAR, ARCHITECT

Jamean

COA REG. NO. CA/97/21582 TCP REG. NO. AR/0064/2010

TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

| Sr. No. | Common areas and Facilities, Amenities | Proposed (Yes/No) | Percentage of work done | Details . |
|---------|---|----------------------|---------------------------------------|---------------------------------------|
| 1. | Internal Roads & Footpaths | Yes | 0% | |
| 2. | Water Supply | Yes | 0% | Govt. PWD Supply |
| 3. | Sewerage (chamber, lines, STP) | Yes | 0% | Septic tank & Soak pit |
| 4. | Storm Water Drains | Yes | 0% | Roadside drains |
| 5. | Landscaping & Tree Planting | Yes | 0% | |
| 6. | Street Lighting | Yes | 0% | LED lights |
| 7. | Community Buildings | No | | |
| 8. | Treatment and disposal of sewage and sullage water | No | | Septic tank & Soak pit |
| 9. | Solid Waste management & Disposal | No | - . | |
| 10 | Water conservation, Rain water harvesting | Yes | 0% | · · · · · · · · · · · · · · · · · · · |
| 11 | | No | - | |
| 12 | Fire protection and fire safety | . No | · · · · · · · · · · · · · · · · · · · | |
| 13 | Electrical meter room, sub-station, receiving station | Yes | 0% | 1 |
| 1. | | Yes | 0% | |
| 1 | 5 Auxiliary Tank | No | - | |
| 1 | 6 Sewerage Collection Tank | Yes | 0% | Septic Tank |
| 1 | 7 Outer Retaining Walls | Yes | 0% | - 4 |
| 1 | 8 Underground Storm Water Line | Yes | 0% | |
| 1 | Underground Cable Line wit Chamber & Chamber Cover | h Yes | 0% | |
| - 2 | 20 Footpath | Yes | 0% | |
| | 21 Watchman Cabin | Yes | 0% | |
| | 22 Entrance Gate | Yes | 0% | |
| _ | 23 Swimming Pool | Yes | 0% | • |
| , · L | 24 Clubhouse With Gym | Yes | 0% | · |
| | Recreation Area Childrens Play Area Indoor Outdoor | & No | - 0% | |

Yours Faithfully TCP REG. No. AR/0064/2010 COAREG. No. CA/97/21582 CT

