### The Goa real Estate (Regulation and Development) (Registration of Real Estate Projects, Registration of Real Estate Agents, Rates of Interest and Disclosures on Website) Rules 2017

#### FORM 1

## (See Rule 5 (1) (a) (ii)) ARCHITECT'S CERTIFICATE

#### Date: 20<sup>th</sup> Feb 2018

To, Boshan Developers Pvt. Ltd. Opp. Shree Bodgeshwar Temple, Mapusa, Bardez – Goa, 403507.

Subject: Certificate of Percentage of Completion of Construction Work of One Number of Residential Cum Commercial Building / Single Wing of the Entire Phase of the Project "Boshan Classic" situated on P.T. Sheet No. 161, Chalta No. 3/ 7,8,9,10,11,12,13&14 demarcated by its boundaries Survey no. 4 /10 of P.T. Sheet No. 161 to the North, Survey no. 3 /3 of P.T. Sheet No. 161 to the South, Mapusa – Calangute Road to the East, Survey no. 3 /6 of P.T. Sheet No. 161 to the West, of Ward No. 20 of Mapusa Municipality, Bardez Taluka, North Goa District, PlN 403507 admeasuring 7538.11 sq.mts., area being developed by Boshan Developers Pvt. Ltd.

**Ref: Goa RERA Registration Number** 

Sir,

I/ We M/s ULYSIS have undertaken assignment as Architect /Licensed Surveyor of certifying Percentage of Completion of Construction Work of One Number of Residential Cum Commercial Building / Single Wing of the Entire Phase of the Project "Boshan Classic" situated on P.T. Sheet No. 161, Chalta No. 3/7,8,9,10,11,12,13&14 of Ward No. 20 of Mapusa Municipality, Bardez Taluka, North Goa District, PlN 403507 admeasuring 7538.11 sq.mts., area being developed by Boshan Developers Pvt. Ltd.

1. Following technical professionals are appointed by Owner / Promoter :-

- (i) M/s. ULYSIS as Architect
- (ii) Shri Rajesh Mahambrey & Associates as Structural Consultant
- (iii) M/s. Engineering Creations Public Health Consultancy as MEP Consultant
- (iv) Shri. Ganpat Gawas as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number

under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

& Landreave Consult

# Table A

# Building

Sr.No.	Tasks / Activity	Percentage of work done 100%	
1	Excavation		
2	One number of Basement (s) and Plinth	100%	
3	Zero number of Podiums	0	
4	Zero number Stilt Floor	0	
5	Eight number of slabs of super structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	65%	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat Premises	75%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	80%	
9	The External Plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/ Wing	90%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	70%	



### Table - B

Sr.No.	Common areas and facilities, amenities	Proposed (Yes / No)	Percentage of work done	Details
1	Internal Roads & Footpaths	Yes	0%	Balance work
				is in progress
2	Water Supply	Yes	0%	Balance work is in progress
3	Sewerage (Chamber, Lines, Septic tank, STP)	Yes	0%	Balance worl
4	Storm Water Drains	Yes	0%	Balance worl is in progress
5	Landscaping & Tree planting	Yes	0%	Balance work is in progress
6	Street Lighting	Yes	0%	Balance wor is in progress
7	Community Buildings	No		
8	Treatment and disposal of sewage and sullage water	Yes	0%	Balance work is in progress
9	Solid Waste Management & Disposal	Yes	0%	Balance wor is in progress
10	Water Conservation, Rain Water Harvesting	No		
11	Energy Management	No		
12	Fire Protection & Fire Safety Requirements	Yes	35%	Balance wor is in progress
13	Electrical Meter Room, Sub- station & Receiving Station	Yes	0%	Balance wor is in progress
14	Gym Equipment & Furnishing	Yes	0%	Balance wor is in progress

## Internal & External Development Works in Respect of the entire Registered Phase

Yours Faithfully

NAIN 20 2/18 AR. SIDDHARTH D. NAIK 201 - A, MATHIAS PLAZA PANAJI - GOA 403 001 REG. NO : AR/0027/2010 COA NO :CA/97 / 21749

FOR M/S ULYSIS (PROPRIETOR)

e