ARCHITECTURE AND DESIGN

FORM 1

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of On-going Project / for withdrawal of Money from Designated Account)

Date: 09th July, 2025

To.

ASHWIN CHOLERA.

Shantilal Real Estate Services, 2nd Floor, Shantilal Retail Park, Dabolim, Goa 403 711

Subject: Certificate of Percentage of Completion of Construction Work of <u>1</u> No. of Building of the Project <u>SAGE BY SHANTILAL</u> situated on the Plot bearing <u>Plot no.</u> <u>01 of Survey No. 31/1-A of Dabolim Village</u> demarcated by its boundaries <u>10.00 M</u> <u>wide road</u> to the North and West side, <u>8.00 M wide road and Plot 02</u> to the East side, <u>Survey no. 31/1 of Dabolim Village</u> to the South, <u>Mormugao Taluka</u>, <u>South Goa District</u>, PIN <u>403 726</u> admeasuring <u>1994.25 sq.mts</u>. area being developed by <u>SHANTILAL REAL ESTATE SERVICES</u>.

Ref: Goa RERA Registration Number (New Registration)

Sir.

I <u>Ar. Vidhya Tapadia</u> have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the Project <u>SAGE BY SHANTILAL</u>, situated on the plot bearing <u>Plot no. 01 of Survey No. 31/1-A of Dabolim Village</u>, <u>Mormugao</u> Taluka, <u>South Goa</u> District, PIN <u>403 726</u> admeasuring <u>1994.25 sq.mts</u>. area being developed by <u>SHANTILAL REAL ESTATE SERVICES</u>

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Ar. Vidhya Tapadia as Architect;
- (ii) Mr. Prathamesh Bhat as Structural Consultant

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number (New Registration) under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

ARCHITECTURE AND DESIGN

Table A

Sr.No.	Tasks/Activity	Percentage of work done	
1	Excavation		
2	1 number of Plinth	0	
3	0 number of Podiums	0	
4	Stilt Floor	0	
5	7 number of Slabs of Super Structure	0	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	0	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0	

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

Sr.No.	Common areas and Facilities,	Proposed	Percentage of	Details
	Amenities	(Yes/No)	work done	
1	Internal Roads & Footpaths	Yes	0	
2	Water Supply	Yes	0	
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	0	
4	Storm Water Drains	Yes	0	
5	Landscaping & Tree Planting	No		
6	Street Lighting	Yes	0	
7	Community Buildings	No		
8	Treatment and disposal of sewage and sullage water	Yes		
9	Solid Waste management & Disposal	Yes		Waste management only
10	Water conservation, Rain water	No		_

ARCHITECTURE AND DESIGN

	harvesting			
11	Energy management	No		
12	Fire protection and fire safety requirements	Yes	0	
13	Electrical meter room, sub-station, receiving station	Yes	0	Electrical Meter Room Only
14	Others (Option to Add more)			•

Yours Faithfully,

AR. VIDADA ŤÄŤ

(License No COA 2004/33047)