

The Goa Real Estate (Regulation and Development) (Registration of Real Estate Projects, Registration of Real Estate Agents, Rates of Interest and Disclosures on Website) Rules 2017

FORM 1 (See Rule 5 (1) (a) (ii)) ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of On-going Project and for withdrawal of Money from Designated Account)

Date: 19th October 2020

To,
V. K. Realtors,
S.No. 110/0, Carapur
Bicholim - Goa.

Subject : Certificate of Percentage of Completion of Construction Work of 2 Nos. Buildings
of the Project "Green Acres" situated on the Plot bearing Survey No. 110/0,
demarcated by its boundariesto the North
to the Southto the Eastto the West, of Ward,
village panchayat Carapur taluka Bicholim District North Goa PIN 403504 admeasuring
12750.00 sq.mts. area being developed by Prop. R. V. Dubhashi.
Ref: Goa RERA Registration Number
Sir,
We Oracle Structural Consultants represented by Shri Rajan L. Prabhu Moye have undertaken
assignment as Architect / Licensed Surveyor of certifying Percentage of Completion of
Construction Work of the 2 Nos. Buildings of the Project "Green Acres" situated on the plot
bearing Survey no. 110/0 of Ward No, village panchayat Carapur, taluka Bicholim, District
North Goa, PIN 403504 admeasuring 12750.00 sq.mts. area being developed by Prop. R. V.
Dubhashi.
Following technical professionals are appointed by Owner / Promoter:-
(i) Oracle Structural Consultants represented by Shri Rajan L. Prabhu Moye as Architect;
(ii) Oracle Structural Consultants represented by Shri Rajan L. Prabhu Moye as Structural Consultant
(iii) M/s /Shri / Smtas MEP Consultant
(iv) M/s /Shri / Smtas Site Supervisor

409 / 410, BLOCK B, SALDANHA BUSINESS TOWERS, OPP. COURT, MAPUSA - GOA. 403507 Tel: 2252730

E-MAIL: rajanmoye@gmail.com



Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number____under GoaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

BUILDING - D

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	100 %	
2	Plinth Level	100 %	
3	number of Podiums	NA	
4	Stilt Floor	0 %	
5	number of Slabs of Super Structure	0 %	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0 %	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0 %	

409 / 410, BLOCK B, SALDANHA BUSINESS TOWERS, OPP. COURT, MAPUSA - GOA. 403507 Tel: 2252730 E-MAIL: rajanmoye@gmail.com



BUILDING - E

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	100 %	
2	Plinth Level	100 %	
3	number of Podiums	NA	
4	Stilt Floor	0 %	
5	number of Slabs of Super Structure	0 %	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0 %	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0 %	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0 %	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	0 %	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0 %	

409 / 410. BLOCK B. SALDANHA BUSINESS TOWERS, OPP. COURT. MAPUSA - GOA. 403507 . Tel: 2252730 E-MAIL: rajanmoye@gmail.com



TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of work done	Details
1.	Internal Roads & Footpaths	YES	70 %	
2.	Water Supply	NO		
3.	Sewarage (chamber, lines, Septic Tank, STP)	YES	40 %	
4.	Storm Water Drains	NO		
5.	Landscaping & Tree Planting	YES	50 %	
6.	Street Lighting	NO		
7.	Community Buildings	YES	40 %	7-
8.	Treatment and disposal of sewage and sullage water	.NO		
9	Solid Waste management & Disposal	NO		
10	Water conservation, Rain water harvesting	NO	L 1	
11	Energy management	NO	· .	
12	Fire protection and fire safety requirements	NO		_
13	Electrical meter room, sub-station, receiving station	NO		
14	Swimming Pool	YES	80 %	

Yours Faithfully

Signature & Name

Rajan L. Prabhu Moye M.E. (Civil), M.I.E.

> Consulting Engineer Reg. No.: SE/0004/2010

Oracle Structural Consultants

Represented by Shri Rajan L. Prabhu Moye as Architect

409 / 410. BLOCK B. SALDANHA BUSINESS TOWERS, OPP. COURT, MAPUSA - GOA, 403507 Tel: 2252730 . E-MAIL: rajanmoye@gmail.com