## FORM 1 ARCHITECTS CERTIFICATE

Date: 18/02/2020

To, Shri D. K. Desai (Promoter) Ponda- Goa

Subject:- Certificate of percentage of completion of construction work of Padma Residency, Row houses in plot no. 18 admeasuring 1025 sq. mts., survey No.258/1 Bandora Village Panchayat demarcated by its boundaries as 10 m. road to East, by open space to west, by plot No. 5,6 and 7 to north and by nalla and open spaces to south in village Bandora ponda, being developed by Shri. Dilip K. Desai

Sir,

I Shri **Machindranath chari** have undertaken assignment as Architect for certifying Percentage of Completion of Construction Work of" Padma Residency", row houses in plot no. 18, S. No. 258/1, Bandora Village Panchayat, Taluka Ponda- Goa 403 401 admeasuring 1025 sq.mts area being developed by Shri D. K. Desai.

- 1. Following technical professionals are appointed by Promoter:-
  - (i) Shri A. A. Vaidya as Civil Engineer;
  - (ii) Shri K. A. Sahakari as Structural Consultant

Based on site Inspection, with respect to each of the Building/ Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Building/ Wing of the Real Estate Project's Registered vide number (applied) under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

## **Table A**

Sr. No.	Tasks/ Activity	Percenta ge of work done		
1.	Excavation	0%		
	number of Basement(s) and Plinth	0%		
2. 3.	number of Podiums	Not applicable		
4.	Still Floor	Not applicable		
5.	number Slabs of Super Structure	0%		
6.	Internal walls, Internal Plaster, Floorings within Flats/ Premises, Doors and Windows to each of the Flat/ Premises	0%		
7.	Sanitary Fittings within the Flat/ Premises  Electrical Fittings within the Flat/ Premises			
8.	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks			
9.	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building/ Wing.	0%		
10.	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment,	0%		

Table B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and	Proposed	Percentage of	Details
	facilities, Amenities	(Yes/ No)	work done	
1.	Internal Roads & Footpaths	YES	0%	
2.	Water Supply	YES	0%	
3.	Sewerage (chamber, lines, Septic Tank, STP)	YES	0%	
4.	Storm Water Drains	YES	0%	
5.	Landscaping & Tree Planting	YES	0%	
6.	Street Lighting	YES	0%	
7.	Community Buildings	NO		
8.	Treatment and disposal of sewage and sullage water	NO		
9.	Solid Waste Management & Disposal	NO		Garbage collected by panchayat
10.	Water conservation, Rain water harvesting	NO		rh routh re
11.	Energy management	NO	0%	
12.	Fire protection and fire safety requirements	NO	0%	
13.	Electrical meter room, sub- station, receiving station	NO	0%	
14.	Others(Option to Add more)			

Yours Faithfully,

MACHINDRANATH R. CHARI ARCHITECT Reg. No. AR/0019/2013

Machindranath Ramesh Chari Architect

(Registration No.CA/2002/28848)