The Goa Real Estate (Regulation and Development) (Registration of Real Estate Projects, Registration of Real Estate Agents, Rates of Interest and Disclosures on Website) Rules 2017

FORM 1

(See Rule 5 (1) (a) (ii)) ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of On-going Project and for withdrawal of Money from Designated Account)

Date: 20.02.2018

To Mr. Anthony Cedric Dias, Proprietor, Prime Builders, 2nd Floor, Prime Corner,

Vasco da Gama,

Goa - 403802

Subject:

Certificate of Percentage of Completion of Construction Work of 1 (one) No. of Building of the Single Phase of the Project "The Miguel-Prime Residency" situated on the two amalgamated Plots bearing Survey nos. 1/1-D and 1/1-E demarcated by its boundaries to the North; by Plot No. 14 bearing Survey No. 1, sub-division No. 1, to the South; by land belonging to Communidade of Sancoale bearing Survey No. 1 sub-division nos. 1 and 2, to the East; by strip of open land and thereafter by road leading to Bogmalo Village and to the West; by 6.00 mtrs. wide sub-division road of Ward 3, Village Panchayat of Chicalim, Mormugao Taluka, South Goa District, PIN 403801 admeasuring 1269 sq.mts. area being developed by Mr. Anthony Cedric Dias, Proprietor of Prime Builders, 2nd Floor, Prime Corner, Vasco da Gama, Goa

Ref:

Goa RERA Registration Number (Fresh Application)

Sir,

I Mr. Anand Prakash have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the 1 (one) Building of the Single Phase of the Project,

Ar. Anand Prakash CA/2001/28028 B.Arch (Goa University) M.CAD-CAM (IMS CAD CAM CENTRE) AR/0096/2011 situated on the two amalgamated Plots bearing Survey nos. 1/1-D and 1/1-E of Ward 3, Village Panchayat of Chicalim, Mormugao Taluka, South Goa District, PIN 403801 admeasuring 1269 sq.mts. area being developed by Mr. Anthony Cedric Dias, Proprietor of Prime Builders, 2nd Floor, Prime Corner, Vasco da Gama

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) Smt. Karen S. Rodrigues as Architect;
- (ii) Shri A. Olavo Carvalho as Structural Consultant
- (iii) M/s /Shri / Smt _____ as MEP Consultant
- (iv) M/s /Shri / Smt _____as Site Supervisor

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building of the Real Estate Project as registered vide number Fresh Application under GoaRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

Table A

Building Number 1 (to be prepared separately for each Building / Wing of the Project)

Sr. No.	Tasks / Activity	Percentage of work done
1	Excavation	100%
2	No. of basement and plinth	100%
3	Number of Podiums	N/A
4	Stilt Floor	100%
5	5 number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	88%
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	80%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	
9	- The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	100%

Ar. Anand Prakash CA/2001/28028 B.Arch (Goa University) M.CAD-CAM (IMS CAD CAM CENTRE) AR/0096/2011

10	Installation of lifts, water pumps, Fire Fighting Fittings and	
	Equipment as per CFO NOC, Electrical fittings to Common	
	Areas, electro, mechanical equipment, Compliance to	
	conditions of environment /CRZ NOC, Finishing to entrance	67%
	lobby/s, plinth protection, paving of areas appurtenant to	
	Building/Wing, Compound Wall and all other requirements as	
	may be required to Obtain Occupation /Completion Certificate	

TABLE-B
Internal & External Development Works in Respect of the entire Registered Phase

Sr.	Common areas and Facilities,	Proposed	Percentage	Details
No.	Amenities	(Yes/No)	of work done	
1	Internal Roads & Footpaths	YES	50%	Soling done,
	ş.			fixing of
				pavers are
				left
2	Water Supply	YES	80%	Internal
				plumbing
				lines are
				completed.
	the Assertion			Connection to
				main line
				remains to be
				done-
3	Sewarage (chamber, lines,	YES	90%	Septic tank
	Septic Tank, STP)			and soak pit
				constructed.
				Connection to
				building lines
				remains.
4	Storm Water Drains	YES	10%	Work in
				progress-
5	Landscaping & Tree Planting	NO	-	-
6	Street Lighting	NO	-	-
7	Community Buildings	NO	-	-
8	Treatment and disposal of	NO	-	-
	sewage and sullage water			

Ar. Anand Prakash CA/2001/28028 B.Arch (Goa University) M.CAD-CAM (IMS CAD CAM CENTRE) AR/0096/2011

9	Solid Waste management &	NO	-	-
	Disposal			
10	Water conservation, Rain water	NO	-	-
	harvesting			
11	Energy management	NO	-	-
12	Fire protection and fire safety	NO	-	-
	requirements			
13	Electrical meter room, sub-station,	YES	60%	Fixing of
	receiving station			electrical
				meter panel
				and errection
				of
				transformer
				centre in
	4.			progress
14	Others (Option to Add more)			

Yours faithfully,

Ar. Anand Prakash
CA/2001/28028
B.Arch (Goa University)
M.CAD-CAM (IMS CAD CAN CENTRE)
AR/0096/2011