## **ARCHITECT'S CERTIFICATE**

Date: 31-01-2022

To
Classic Squares Reality Pvt Ltd
5th Floor, Fortune Square Building,
Morod, Mapusa, Bardez Goa -403507.

**Subject:** Certificate of Percentage of Completion of Construction Work of <u>Residential Building</u> situated on the Plot bearing PTS No. 26, Chalta No. 16-C demarcated by Rain Water Nallah to the North, by its Boundary 10.00 mt. wide Road to the East, by Adjoining Property to the South, by Rain Water Nallah to the West of Ward <u>Xelpem Duler</u> Municipality <u>Mapusa</u> taluka <u>Bardez</u> District <u>North</u> PIN 403507 admeasuring 1,463. Sq.Mtr. area being developed by Classic Squares Reality Pvt Ltd.

Sir,

We <u>M/S ULYSIS</u> have undertaken assignment as Architect certifying Percentage of Completion of Construction Work of <u>Residential Building</u> situated on the Plot bearing PTS No. 26, Chalta No. 16-C demarcated by Rain Water Nallah to the North, by its Boundary 10.00 mt. wide Road to the East, by Adjoining Property to the South, by Rain Water Nallah to the West of Ward <u>Xelpem Duler</u> Municipality <u>Mapusa</u> taluka <u>Bardez District North PIN 403507</u> admeasuring <u>1,463</u>. Sq.Mtr. area being developed <u>by Classic Squares Reality Pvt Ltd.</u>

- 1. Following technical professionals are appointed by Owner / Promoter:-
- (i) M/s <u>ULYSIS</u> (Sidharth Naik) as Architect;
- (ii) M/s Rajesh Mahembrey & Associates as Structural Consultant
- (iii) M/s /Shri / Smt ----- as MEP Consultant
- (iv) M/s Rajesh Mahembrey & Associates as Quantity Surveyor \*

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number \_\_\_\_\_ under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

3/1/22

## Table A

## **Building**

Sr. No	Tasks /Activity	Percentage of work done	
1	Excavation	0%	
2	Zero number of Basement(s) and Plinth	0%	
3	Zero number of Podiums	0%	
4	One Stilt Floor	0%	
5	Five number of Slabs of Super Structure	0%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	0%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%	



**TABLE-B** Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of work done	Details
1.	Internal Roads & Footpaths	YES	0%	
2.	Water Supply	YES	0 %	
3.	Sewerage (chamber, lines, Septic Tank, STP)	YES	0 %	
4.	Storm Water Drains	YES	0 %	
5.	Landscaping & Tree Planting	YES	0 %	
6.	Street Lighting	YES	0 %	
7.	Community Buildings	NO		
8.	Treatment and disposal of sewage and sullage water	NO		
9	Solid Waste management & Disposal	NO		
10	Water conservation, Rain water harvesting	NO		
11	Energy management	NO		
12	Fire protection and fire safety requirements	NO		
13	Electrical meter room, sub-station, receiving station	YES	0%	
14	Others (Option to Add more)			

PANAJI - GOA 403 001 REG. NO: AR/0027/2010 COA NO :CA/97 / 21749

FOR M/S ULYSIS (PROPRIETOR)