The Goa Real Estate (Regulation and Development) (Registration of Real Estate Projects, Registration of Real Estate Agents, Rates of Interest and Disclosures on Website) Rules 2017

<u>FORM 1</u>

(See Rule 5 (1) (a) (ii)) ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of On-going Project and for withdrawal of Money from Designated Account)

Date: 06/04/2022

To M/s M. G. Developers Office No. 6-B, R R Tower, Angod, Mapusa Goa, 403507

Subject: Certificate of Percentage of Completion of Construction Work of "R.R.Heritage" Project situated on the Plot bearing Survey No. 102/1-B demarcated by its boundaries

East: By property under survey No.102/1 of village Carapur,

West: By property under survey No.102/1-A of village Carapur,

North: By main road Sankhali-Bicholim,

South: By property under Survey No.102/1 of village Carapur

Situated at village panchayat Karapur-Sarvan, Taluka Bicholim, district North Goa , PIN 403505, admeasuring 3010 sq.mts. area being developed by M/s R.R Enterprises.

Ref: Goa RERA Registration Number PRG006211325

Sir,

I Shivastu [Arch. Sitaram S. Gawas] have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of R R Heritage Project situated on the plot bearing Survey no.102/1-B Situated at village panchayat Karapur-sarvan, Taluka Bicholim, District North Goa,403505, admeasuring 3010sq.mts.area being developed by M/s R.R Enterprises.

- 1. Following technical professionals are appointed by Owner / Promoter :-
 - (i) Shivastu[Arch. Sitaram S Gawas] as Architect;
 - (ii) Mr. Ravindra Palyekar as Structural Consultant

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project , I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real Estate Project as registered vide number __PRG006211325 ___ under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

R R Heritage

Sr. No	Tasks /Activity	Percentage of work done	
The second secon	Excavation	98%	
2	1 number of Basement(s) and Plinth	100%	
3	0 number of Podiums	NA-	
4	Stilt Floor	100%	
5	5number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	98%	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	70%	
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	95%	
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing,	90%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	80%	

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

Sr. No.	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of work done	Details
1.	Internal Roads & Footpaths	Yes	80%	
	Maton Cupply	Yes	70%	
2.	Water Supply Sewerage (chamber, lines, Septic	Yes	70%	
3.	Tank, STP)			
4.	Storm Water Drains	Yes	30%	
5.	Landscaping & Tree Planting	No	0	Not started yet
6.	Street Lighting	No	0	Not fixed
7.	Community Buildings	No	100%	

14.	13.	13	13		10 :	e
Others (Option to Add more)	receiving station	requirements	Einergy management	harvesting	Disposal	Sewage and sullage water
No	Yes	Zo	No	No	NO	No
0	0%	NA	NA	NA		NA.
	Not started	Z	VN		Under construction	

Yours Faithfully

Shivastu
(Arch. Sitaram S. Gawas)
(License NO......

