FORM-1 See Rule 5 (1) (a) (ii) ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of On-going Project and for withdrawal of Money from Designated Account- Project wise)

Date: 25-04-2022 To. Nanu Estates Pvt. Ltd., Nanu House, V.V. Road, Margao, Goa. Subject: Certificate of Percentage of Completion of Construction Work of SEVEN No. of Villa(s) of the FIRST & SECOND Phase of the Project THE BANYAN TREE situated on the Plot bearing Survey no. 72/1-A demarcated by its boundaries; AN OPEN PLOT to the North A 6.0M WIDE ACCESS ROAD to the South AN OPEN PLOT to the East AN OPEN PLOT to the West, of village panchayat SIOLIM, taluka BARDEZ, PIN 403517 admeasuring 2000 sq.mts. area being developed by Nanu Estates Pvt. Ltd. Ref: Goa RERA Registration Number Sir, We Arijeet Raikar Design Studio have undertaken assignment as Architect of certifying Percentage of Completion of Construction Work of the SEVEN No. of Villa(s) of the FIRST & SECOND Phase of the Project THE BANYAN TREE situated on the Plot bearing Survey no. 72/1-A of village panchayat SIOLIM, taluka BARDEZ, PIN 403517 admeasuring 2000 sq.mts. area being developed by Nanu Estates Pvt. Ltd. 1. Following technical professionals are appointed by Owner / Promoter: -(i) Shri Arijeet Raikar of Arijeet Raikar Design Studio (ARDS) as Architect; (ii) Shri Yogesh Bhobe of M/s Siddhyog Constructions as \$tructural Consultant (iii) Shri Nilesh Powar as Site Supervisor Based on Site Inspection, with respect to the Villas of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real under GoaRERA is as per table A Estate Project as registered vide number _____

ARIJEETRAIKAR**DĘSIGNSTUDIO**

H.No: 1578/1, Near Post & Telegraph Colony, Alto Porvorim - Bardez, Goa, Phone - 9822984382 Email - office@ards.design PAN Number AIRPR4982R / GSTIN : 3DAIRPR4982R1Z7 herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B.

TABLE A

Villa Number A1

Sr No.	Tasks/ Activity	Percentage of Work Done
1	Excavation	100%
2	ZERO number of Basement(s) and ONE number of Plinth	100%
3	ZERO number of Podiums	N.A.
4	Stilt Floor	N.A.
5	TWO number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the	50%
7	Flat/Premises Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	50%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

ARIJEETRAIKAR**DESIGNSTUDIO**

Villa Number A2

Sr No.	Tasks/ Activity	Percentage of Work Done	
1	Excavation	100%	
2	ZERO number of Basement(s) and ONE number of Plinth	100%	
3	ZERO number of Podiums	N.A.	
4	Stilt Floor	N.A.	
5	TWO number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within	50%	
	Flats/Premises, Doors and Windows to each of the		
	Flat/Premises	00/	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%	
8	Staircases, Lifts Wells and Lobbies at each Floor level	100%	
	connecting Staircases and Lifts, Overhead and		
	Underground Water Tanks		
9	The external plumbing and external plaster, elevation,	50%	
	completion of terraces with waterproofing of the Building /		
	Wing		
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0%	
	Equipment as per CFO NOC, Electrical fittings to Common		
	Areas, electro, mechanical equipment, Compliance to		
	conditions of environment /CRZ NOC, Finishing to entrance		
	lobby/s, plinth protection, paving of areas appurenant to		
	Building/Wing, Compound Wall and all other requirements		
	as may be required to Obtain Occupation /Completion		
	Certificate		

Villa Number A3

Sr No.	Tasks/ Activity	Percentage of Work Done	
1	Excavation	100%	
2	ZERO number of Basement(s) and ONE number of Plinth	100%	
3	ZERO number of Podiums	N.A.	
4	Stilt Floor	N.A.	
5	TWO number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Floorings within	50%	
	Flats/Premises, Doors and Windows to each of the		
	Flat/Premises		
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings	0%	
	within the Flat / Premises		
8	Staircases, Lifts Wells and Lobbies at each Floor level	100%	
	connecting Staircases and Lifts, Overhead and		
	Underground Water Tanks		
9	The external plumbing and external plaster, elevation,	50%	
	completion of terraces with waterproofing of the Building /		
	Wing		
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0%	
	Equipment as per CFO NOC, Electrical fittings to Common		
	Areas, electro, mechanical equipment, Compliance to		
	conditions of environment /CRZ NOC, Finishing to entrance		
	lobby/s, plinth protection, paving of areas appurenant to		
	Building/Wing, Compound Wall and all other requirements		
	as may be required to Obtain Occupation /Completion		
	Certificate		

Villa Number A4

Sr No.	Tasks/ Activity	Percentage of Work Done
1	Excavation	100%
2	ZERO number of Basement(s) and ONE number of Plinth	100%
3	ZERO number of Podiums	N.A.
4	Stilt Floor	N.A.
5	TWO number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Floorings within	50%
	Flats/Premises, Doors and Windows to each of the Flat/Premises	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	50%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Villa Number B

Sr No.	Tasks/ Activity	Percentage of Work Done
1	Excavation	100%
2	ZERO number of Basement(s) and ONE number of Plinth	100%
3	ZERO number of Podiums	N.A.
4	Stilt Floor	N.A.
5	TWO number of Slabs of Super Structure	50%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Row Villa Number C1

Sr No.	Tasks/ Activity	Percentage of Work Done
1	Excavation	0%
2	ZERO number of Basement(s) and ONE number of Plinth	0%
3	ZERO number of Podiums	N.A.
4	Stilt Floor	N.A.
5	TWO number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0%
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings within the Flat / Premises	0%
8	Staircases, Lifts Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0%
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building / Wing	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	0%

Row Villa Number C2

Sr No. Tasks/ Activity		Percentage of Work Done
1	Excavation	0%
2	ZERO number of Basement(s) and ONE number of Plinth	0%
3	ZERO number of Podiums	N.A.
4	Stilt Floor	N.A.
5	TWO number of Slabs of Super Structure	0%
6	Internal walls, Internal Plaster, Floorings within	0%
	Flats/Premises, Doors and Windows to each of the	
	Flat/Premises	
7	Sanitary Fittings within the Flat / Premises, Electrical Fittings	0%
	within the Flat / Premises	
8	Staircases, Lifts Wells and Lobbies at each Floor level	0%
	connecting Staircases and Lifts, Overhead and	
	Underground Water Tanks	
9	The external plumbing and external plaster, elevation,	0%
	completion of terraces with waterproofing of the Building /	
	Wing	
10	Installation of lifts, water pumps, Fire Fighting Fittings and	0%
	Equipment as per CFO NOC, Electrical fittings to Common	
	Areas, electro, mechanical equipment, Compliance to	
	conditions of environment /CRZ NOC, Finishing to entrance	The state of the s
	lobby/s, plinth protection, paving of areas appurtenant to	
	Building/Wing, Compound Wall and all other requirements	
	as may be required to Obtain Occupation /Completion	
	Certificate	

TABLE B

Internal & External Development Works in Respect of the entire Registered Phase

Sr	Common areas and Facilities,	Proposed (Yes/	Percentage of	Details
No.	Amenities	No)	Work Done	
1	Internal Roads & Footpaths	YES	0%	
2	Water Supply	YES	0%	
3	Sewerage (chamber, lines, Septic Tank, STP)	YES	0%	
4	Storm Water Drains	YES	0%	
5	Landscaping & Tree Planting	YES	0%	
6	Street Lighting	YES	0%	
7	Community Buildings	NO	N.A.	
8	Treatment and disposal of sewage and sullage water	NO	N.A.	
9	Solid Waste management & Disposal	NO	N.A.	
10	Water conservation, Rain water harvesting	NO	N.A.	
11	Energy management	NO	N.A.	
12	Fire protection and fire safety requirements	NO	N.A.	
13	Electrical meter room, sub-station, receiving station	NO	N.A.	
14	Others (Option to Add more)		N.A.	

Yours Faithfully

ARIJEET RAIKAR (B. Arch)

H. No: 1578/1, NEAR POST & TELEGRAPH COLONY ALTO-PORVORIM, BARDEZ-GOA
COA REGISTRATION: CA/2007/39585

GOA REGISTRATION : AR/0051/2011

Signature & Name (IN BLOCK LETTERS) of Architect (License NO.....)

ARIJEETRAIKAR**DESIGNSTUDIO**

H.No: 1578/1, Near Post & Telegraph Colony, Alto Porvorim - Bardez, Gda, Phone - 9822984382 Email - office@ards.design PAN Number AIRPR4982R / GSTIN : 30AIRPR4982R1Z7