Viraj Dessai

Architect & Interior Planner
O-101, First Floor, Prime Elite, Nr. Urvashi Hotel, Vasco – Goa.
Contact: 0832-2500906, 9823363993, Email: virajdessai@rediffmail.com

Date: 08.08.2019

TO WHOMSOEVER IT MAY CONCERN

To

Prime Builders and Sakaria Life Space, 2nd Floor, Prime Corner, Vasco, Mormugao - Goa. 403802.

Subject: Certificate of Percentage of Completion of Construction Work of Residential building, (RERA Registration Number <u>Applied For</u>) situated on plot of land, <u>Surveyed Under Chalta No. 12</u>, 13 and 15 of P.T.Sheet No. 94, at Vaddem – Vasco, Taluka Mormugao, District South Goa, Goa PIN 4037802 admeasuring 2553.00 sq. mtr area being developed by Prime Builders and Sakaria Life Space.

Sir,

I Ar. Viraj Dessai have undertaken assignment as Architect certifying Percentage of Completion of Construction Work of your Residential cum Commercial Building, (RERA Registration Number <u>Applied For</u>) situated on plot of land, <u>Surveyed Under Chalta No. 12, 13 and 15 of P.T.Sheet No. 94, at Vaddem – Vasco, Taluka Mormugao, District South Goa, Goa PIN 4037802 admeasuring 2553.00 sq. mtr area being developed by Prime Builders and Sakaria Life Space</u>

Following technical professionals are appointed by Owner / Promoter :-

- (i)) Ar. Viraj Dessai as Architect;
- (ii) Eng. Olavo Carvalho as Structural Consultant
- (iii) Mr. Prakash Nadiger as Site Engineer

Based on Site Inspection, with respect to each of the Building/Wing of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the building/Wing of the Real

ARCHITECT ARCHITECT VIRAJ DESSAI VIRAJ DESSAI VIRAJ DESSAI Estate Project as registered vide number under RERA is as per table A herein below. The percentage of the work done executed with respect to each of the activity of the entire phase is in Table B.

Table A
Building /Wing Number 01

Sr. No	Tasks /Activity	Percentag e of work done
1	Excavation	60.0%
2	01 number of Plinth	50.0%
3	00 number of Podiums	0.0%
4	Stilt Floor	0.0%
5	Slabs of Super Structure	0.0%
6	Internal walls, Internal Plaster, Floorings within Flats/Premises, Doors and Windows to each of the Flat/Premises	0.0%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/Premises	0.0%
8	Staircases, Lifts Wells, and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.0% -
9	The external plumbing and external plaster, elevation, completion of terraces with waterproofing of the Building/Wing,	0.0%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment /CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building/Wing, Compound Wall and all other requirements as may be required to Obtain Occupation /Completion Certificate	. 0.0%

MOUNT ARCHITECT ARCHITECT ARCHITECT VIRAJ DESSAI VIRAJ VI

TABLE-B Internal & External Development Works in Respect of the entire Registered Phase

Sr. No	Common areas and Facilities, Amenities	Proposed (Yes/No)	Percentage of Work done	Details
1	Internal Roads & Footpaths	Yes	0.0%	
2	Water Supply	Yes	0.0%	
3	Sewerage (chamber, lines, Septic Tank, STP)	Yes	0.0%	***************************************
4	Storm Water Drains	No	0.0%	
5	Landscaping & Tree planting	No	NA	
6	Street Lighting	No	NA	
7	Community Buildings	No	NA	
8	Treatment and disposal of sewage and sullage water	No	· NA	
9	Solid Waste management & Disposal	No	NA	
10	Water conservation, Rain water harvesting	No	NA	
11	Energy management	No	NA	
12	Fire protection and fire safety requirements	Yes	00%	
13	Electrical meter room, sub-station, receiving station	No	NA	
14	Others (Option to Add more)	No	NA	

Yours Faithfully,

ARCHITECT VIRAJ DESSAI VIRAJ DES2011 Ar. Viraj Dessai