

5th Floor, 'Susheela', F.L. Gomes Road, Vasco da Gama, Goa 403802
Tel.. +91 832 2511110 Fax:+91 832 2512987 Email: nileshsalkarassociates@gmail.com
The Goa Real Estate (Regulation and Development) (Registration of Real
Estate Projects, Registration of Real Estate Agents, Rates of Interest and
Disclosures on Website) Rules 2017

FORM 1
(See Rule 5 (1) (a) (ii))
ARCHITECT'S CERTIFICATE

Date: 17th Jan 2019

To M/s Susheela Homes & Properties Pvt Ltd 5th Floor, Susheela Bldg, Vasco da Gama

Subject: Certificate of Percentage of Completion of Construction Work of THE RESIDENTIAL BUILDING COMPOUND WALL AND SWIMMING POOL of the Project **SUSHEELA VERDANTE** situated on the Plot bearing Survey no. 65/5 of Moira Village demarcated by its its boundaries to the North: by land of Communidade of Moira, to the South:by public road, to the East:by land of Communidade of Moira, to the West:by land of Communidade of Moira of Village Panchayat Moira, Taluka Bardez District South Goa PIN 4035007 admeasuring 1850 sq.mts. area being developed by M/s Susheela Homes & Properties Pvt Ltd.

Ref: Goa RERA Registration Number (not yet allotted)

Sir,

I/ We NILESH SALKAR ASSOCIATES having reg. No AR/0104/2011 & Council of Architects No CA/89/12746 have undertaken assignment as Architect of certifying Percentage of Completion of Construction of THE RESIDENTIAL BUILDING COMPOUND WALL AND SWIMMING POOL of the Project SUSHEELA VERDANTE situated on the Plot bearing Survey no. 65/5 of Moira Village, Taluka Bardez, District North Goa PIN 403507 admeasuring 1850 sq.mts. area being developed by M/s Susheela Homes & Properties Pvt Ltd.

- 1. Following technical professionals are appointed by Owner/Promoter:-
- (i) Shri Arminio Ribeiro De Santana as Architect;
- (ii) Shri Abhijeet D Salkar & Shri Krishna Sahakari as Structural Consultant
- (iii) Shri Ashok Joshi as MEP Consultant

Based on Site Inspection, with respect to the Building of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for the Building of the Real Estate Project as registered vide number (not yet allotted) under Goa RERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in Table B

Nilesh Selker Associates CA/89/12746 AR/0104/2011



Building (to be prepared separately for each building of the Project)

| Sr No | Task/ Activity | Percentage of work done 0% | |
|-------|---|----------------------------------|--|
| 1 | Excavation | | |
| 2 | Plinth | 0% | |
| 3 | 2 number of slabs of super structre | 0% | |
| 4 | Internal walls, Internal Plaster, Floorings within the flats.Doors and Windows for each flat. | 0% | |
| 5 | Sanitary fittings within the flat, Electrical fittings within the flat | 0% | |
| 6 | Staircases, Lifts Wells and Lobbies at each floor level connecting staircases and lifts. Overhead and Underground Water Tanks | 0% | |
| 7 | The external Plumbing and external plaster, elevation, completion of terraces with waterproofing of the villa | 0% | |
| 8 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipment as per CFO NOC, Electrical fittings to Common Areas, electro, mechanical equipment, Compliance to conditions of environment / CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to the Villa Compound Wall and all other requirements as may be required to Obtain Occupation / Completion Certificate. | 0% | |

TABLE-B

Internal & External Development Works in Respect of the entire Registered Phase

| Sr No | Common areas & facilities, amenities | Proposed (Yes/No) | Percentage of work done | Details |
|-------|---|----------------------|-------------------------|---------|
| 1 | Internal Roads & Footpaths | YES | 0% | |
| 2 | Water Supply | YES | 0% | |
| 3 | Sewarage (chamber, lines, septic tank, STP) | YES | 0% | |
| 4 | Storm water drains | YES | 0% | |
| 5 | Landscaping & Tree Planting | YES | 0% | |
| 6 | Street Lighting | YES | 0% | |
| 7 | Community Building (Community center & Swimming Pool) | YES | 0% | |
| 8 | Disposal of sewage and sullage water. (septic tank & soak pit) | YES | 0% | |
| 9 | Solid waste management & disposal | YES | 0% | |
| 10 | Water conservation rain water harvesting | NO | 0% | |
| 11 | Energy management | NO | 0% | |
| 12 | Fire Protection and fire safety requirements | YES | 0% | \ |
| 13 | Electrical meter room, sub-station, receiving station | NO | 0% | |
| 14 | Others (option to add more) | | 0% | |

Yours Faithfully

Signature & Name of Architect

NILESH D SALKAR

NILESH D SALKAR

AR/0104/2011